

Nondestructive Engineering

Performance of In-pavement Runway Light Fixture Assemblies

October 20, 2015

Julia H. Grogan

Senior Engineer

Background

 Incidents involving dislodged in-pavement runway lights

 Comprehensive engineering assessment performed in order to mitigate future light fixture issues



LPI Evaluation Overview

- Light Fixture and Bolt Failure Analyses
- Sampling Program
- Finite Element Analyses
- Torque Testing
- Instrumentation
- Recommendations and Findings

Light Fixture Assemblies

- 8-in. optical housing with 12-in. support ring
- Type 304 SS, Type 410 SS, coated carbon steel bolts



Incident Light Fixture Failure Analysis

Incident Light Fixtures









Fractured Bolts









Airport Site Inspections









Sampling Program

Sampling Program Protocol

- 30 light fixtures selected per runway for inspection:
 - Runways: 9
 - Fixtures: 270
 - Bolts: 1620
- Protocol for Sampling Program included:
 - Visual examination of light fixture
 - Removal of bolts for examination at LPI
 - Visual examination and count of spacer rings
 - Visual examination of bolt holes in extension or base mounting can



Sampling Program Findings

- 22 cracked bolts found
 - Consistent with low-cycle, high-stress fatigue
- 36 bent bolts (Type 304 and Grade 2) found
- Some coated carbon steel bolts exhibited extensive corrosion
- 25 to 50% of support ring holes exhibited thread impressions
- Six extension collars exhibited missing bolts
 - Three base cans exhibited ovalization
- 30 to 45% of light fixtures had more than three spacer rings

Sampling Program Findings





Thread root cracks

Sampling Program Findings



Extension Collar to Base Can Bolt



Finite Element Analyses

Finite Element Analyses

- Evaluate effect of aircraft roll-over on light fixture and support ring bolts
- FEA model created for light fixture assembly
- Loads derived from Aircraft Characteristics documents
 - Considered conservative





FEA Results

	With Foundation Stiffness			Without Foundation Stiffness		
Bolt Preload (lb) $ ightarrow$	<u>2000</u>	<u>3000</u>	<u>5000</u>	<u>2000</u>	<u>3000</u>	<u>5000</u>
<u>Axial [lb]</u>	3029	3849	5033	3311	4067	5156
<u>Shear [lb]</u>	411.3	250.0	71.9	491.0	244.2	117.0
<u>Moment [lb-in.]</u>	476.2	283.4	82.1	558.1	278.1	133.1
<u>Bending Stress</u> [ksi]**	156.5	93.1	27.0	183.4	91.4	43.8
Bolt Z-Disp. [in.]	0.0346	0.0203	0.0065	0.0394	0.0201	0.0103

** Note: This is an "apparent" stress and is only listed for comparison purposes. Once the bolt starts to yield, the linear relationship no longer holds.

Low preload allows slip at Support Ring / Flange Ring interface

FEA Results



Additional FEA Studies





 Effect of spacer rings

 Bolt displacement and bending stress increases with number of rings



- Effect of missing bolt
 - One missing bolt results in higher stresses in remaining bolts

Bolt Torque Testing

Bolt Torque Specifications

- FAA AC 150/5345-42, 150/5340-26, 150/5340-30
 - Torque per manufacturer's recommendations
 - 185 in.-lb (15 ft-lb), 230 in.-lb (18 ft-lb)
- FAA Engineering Brief No. 83

 18-8 bolt (dry): 185 in.-lb (15 ft-lb) maximum
 Coated Grade 2 bolt (dry): 120-144 in.-lb (10-12 ft-lb)
- FAA AC 150/5345-46
 - Light fixture bolts must withstand shear load of 3000 lb

Design Torque vs. Bolt Preload

$$T_{in} = F_P \times D \times K$$

where $T_{in} = \text{input torque (in.-lb)}$

- F_P = achieved preload (lb)
 - D =nominal diameter (in.)
 - K =nut factor



Nut Factor "K"

Experimental constant

- Steel (dry) = 0.2
- Steel (lubricated) = 0.1-0.2

Bickford, John H. *An Introduction to the Design and Behavior of Bolted Joints*. 3rd ed. New York: Marcel Dekker, Inc., 1995. Print. 21

Design Torque vs. Bolt Preload

• Scatter in preload achieved at a uniform torque level



Bickford, John H. *An Introduction to the Design and Behavior of Bolted Joints*. 3rd ed. New York: Marcel Dekker, Inc., 1995. Print.

 Preload uncertainty (Γ) documented in NASA NSTS 08307

Torque-measurement of unlubricated bolts

 $\Gamma = \pm 35\%$

Torque-measurement $\Gamma = \pm 25\%$ of lubricated bolts

Design Torque vs. Bolt Preload

- 3/8 in.-16 Grade 2 carbon steel
 - -75% of proof load = ~ 3200 lb
 - Torque required to achieve 3200 lb pre-load (dry bolt) = 20 ft-lb
- 3/8 in.-16 Type 304 stainless steel
 - 75% of yield load = 3780 lb
 - Torque required to achieve 3780 lb pre-load (dry bolt) = 23 ft-lb
- 3/8 in.-16 Type 410 stainless steel
 - 75% of yield load = 5230 lb
 - Torque required to achieve 5230 lb pre-load (dry bolt) = 32 ft-lb

Torque Test Set-up

• Strain-gaged bolts tested in light fixture assembly



Types of bolts tested:

- Coated Grade 2 carbon steel
- Type 304 stainless steel
- Type 410 stainless steel



Grade 5 carbon steel



- Types of light bases tested:
- L-868 Class IA and IB

Torque Test Results – Grade 2



25

Torque Test Results – Type 304



Torque Test Results – Grade 5



27

Torque to Failure



28

Light Fixture Bolt Recommendations

Bolt Recommendations

- Type 410 stainless steel bolts (ASTM F593P)
 - 23 ft-lb
 - Torque bolts in star pattern
 - Loctite marine grade anti-seize
 - Two-piece lock washer (Nord-lock type)
- Maximum of three spacer rings
 - No silicone sealant
- Check torque after two weeks, then regular maintenance

Light Fixture Instrumentation



- No indication of direct impact, but good results obtained from "rolling end" of runway
- Results indicate aircraft <u>does not</u> have to contact light fixture in order to induce cyclic strain response
- Bolts repeatedly experience 100 to 1500 lb or possibly more relaxation/unloading
 - Utilizing LPI torque vs. preload correlation, 12 ft-lb or more cyclic relaxation/unloading is occurring

- 777 after landing (all wheels down)
 - Centerline bolt strain gages





- 737 after landing (all wheels down)
 - Centerline bolt strain gages





Torque to Failure



36

Simultaneous response at centerline and touchdown zone



Centerline horizontal laser transducer

- Approximately 0.006 in. maximum movement



Collar Strain

Gage

Instrumentation – Continued Work

- Plan to instrument three additional light fixtures
 - -Two runways, one taxiway
 - Data acquisition targeted for late November

• Currently working on pavement and light fixture FEA to further evaluate/validate instrumentation



LPI Evaluation Findings

LPI Evaluation Findings

- Mechanical performance of fixture assemblies
 - Aircraft loading
 - Light fixture installation
 - Maintenance
- Benefit to increasing torque value (preload) of light fixture support ring bolts
 - Recommended torque value should be determined experimentally
 - Maintenance of extension collar to base can bolts

LPI Evaluation Findings

- Light fixture and pavement act as a system
 - Direct wheel contact not required for strain response
 - Continue investigation into light fixture/pavement interaction
- Requires cooperation between airports, FAA, suppliers

Questions?